

MEDIA INFORMATION / PUBLIC INFORMATION WORKSHEET

Please email to PIO Larry Gallegos at lagallegos@bernco.gov (505) 228-6668

1.	Date/Incident number	02/02/2017
2.	Incident Address	2017-001804 Sedillo Rd @ NM 333
۷.	meident Address	Sedillo Kd @ NM 555
3.	Area of County	East Mountains
4.	Mutual Aid request/given	Requested aid from Edgewood, but cancelled enroute
5.	Reported by:	Property owner
6.	Fire Condition/Alarms	Light smoke from roof
	(working fire, 2 nd alarm)	
7.	Size & Type of	Small single story residential structure
	Structure/Incident	
8.	(apt/residential home/ bldg) Number of Personnel	Det 9 E 25 Tr 46 E 22 E 20 D 24 D 26
8.		Bat-8, E-35, Tn-46, E-33, E-30, R-34, R-36 16 personnel
9.	Responded (Units and FFs) Time Dispatched/1st Unit	18:43
9.	Arrival time	18:58
10	Brief description of what 1 st	Units observed light smoke coming from the roof with the property
10.	unit on the scene saw.	owner attempting to fight the fire on the roof.
11.	Total time to bring fire under	12 minutes
	control	
12.	Anyone inside at the time of	Yes, one person
	the fire. If yes, how many	
13.	How was family alerted?	Unknown
1.4	(smoke detector, neighbors)	AY
14.	Injuries? If yes, include age,	None
	gender, transport info & injuries sustained.	
15.	Fire Origin? Was it contained	Failure of wood burning stove components/improper maintenance
	to origin?	causing attic fire
		Ç
16.	Spread through %	< 1%
17	G 1 D 4'11 1	***
17.	Smoke Damage (light or heavy	Light
10	smoke damage throughout) Cause	Improper maintenance of wood burning stove
10.	(determinded/undetermined	improper maintenance of wood ourning stove
	>accident,natural,incendiary)	
19.	Estimated Damages	\$500.00
	(structural, contents/vehicle)	
20.	Assisting Agencies like	None
	Red Cross, # of displaced?	
21.	Contributing factors such as	None
	wind or location	YY !
22.	Additional information	Units were in process of backfilling fire and rescue response to east
	(rescues, FF injuries and so	mountains due to concurrent commercial structure fire. This resulted in a
22	on) On Scene POC	delay of arrival to scene.
	Community Risk Reduction	Ensure wood burning stove, and fireplaces are properly cleaned and
۷4.	Message	inspected/maintained by certified chimney sweep
25	Additional Information	inspected indifficulties of continued cinimity sweep
	. Louisional Information	